



TURF REINFORCEMENT MAT ON A SLOPE


(SESC-50)



OVERVIEW OF TURF REINFORCEMENT MAT ON A CHANNEL BANK



INITIAL TRENCH AT TOP OF SLOPE DETAIL



TERMINAL TRENCH AT TOE OF SLOPE DETAIL

SEE DETAIL SESC-47 AND SESC-51